

Table of Contents

Version 1.1.1 (V1.1.1_160921) 1

Release 1

Bug fixes 1

Version 1.1.1 (V1.1.1_160921)

Release

2016-09-22

Bug fixes

1. Memory leak issue when a T&A device is registered as a slave device and users authenticate after pressing a T&A key.
2. Issue where the master device reboots when a device with an old firmware version is connected as a slave device and a user authenticates with a card on the slave device.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_111

Last update: **2021/05/17 16:55**