

# Table of Contents

1.0.4 Version (V1.0.4_210303) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fixes .....	1

## 1.0.4 Version (V1.0.4\_210303)

### Release

2021-03-10

### New Features and Improvements

#### 1. Changes to a new LCD screen

For devices with firmware version 1.0.3 or earlier, be sure to upgrade the firmware to the latest version before replacing it with a new LCD display. If you upgrade the firmware to version 1.0.4 or higher after replacing the LCD display first, a touch malfunction may occur.

#### 2. Suprema Thermal Camera (TCM10-FSF2) SDK Revision

- FPS 8.3 applied
- The management service is separated to recover the system safely after the device stops working abnormally.
- The infrared image motion stopped working or the device was restarted while using the thermal camera.
- The specifications of captured image buffer were modified.

### Bug Fixes

1. The firmware version of the thermal camera was not displayed.
2. The previous T&A code setting was maintained even after changing the setting.
3. A timeout occurred when a user set to Exclude Device Default Authentication Mode attempted to authenticate a card on a slave device with authentication mode set to Card+PIN.
4. The thermal camera froze up when updating resources via BioStar 2.
5. Improved the Visual Face matching algorithm.
  - Improved the face recognition algorithm for users with glasses.
  - Improved the authentication performance when wearing masks.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2\\_revision\\_note\\_104&rev=1635896389](https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_104&rev=1635896389)

Last update: **2021/11/03 08:39**