# **Table of Contents**

Version 1.3.0 (V1.3.0_190626)	
Release	
Main Fixes	

# Version 1.3.0 (V1.3.0\_190626)

#### Release

2019-07-12

### **New Features and Improvements**

- 1. OSDP Standardization
- Improved to comply with OSDP V2.1.7 protocol when connecting with 3rd-party controllers.
- 2. Supports Anti-Tailgating.
- 3. Supports setting options for Wiegand authentication result output.
- User ID and Card ID
- 4. Increase of the number of administrators that can be added.
- 5. Increase of the maximum number of floor levels.
- **6**. Supports options for selection by card type.
- 7. Support to the Clear APB for each user.
- 8. Supports checking module firmware version.
- 9. Supports the latest version of I/O module Micom (V1.3.1).
- 10. Firmware upgrade status is added to LED status indicator.
- 11. Support for connecting new devices.
- XPass 2(XP2-MDPB, XP2-GDPB, XP2-GKDPB)

#### **Main Fixes**

- 1. When a door configured in a Scheduled Unlock Zone is opened by a Scheduled Unlock, the door is not locked if the zone is deleted.
- 2. A code is added to prevent the authentication fails because the cache memory is broken.

## **Bug Fixes**

- 1. The device recognizes the iCLASS Seos card as a CSN card.
- 2. It does not respond to inputs from the slave device when booting the master device.
- 3. Applies FA improvement algorithm.

- 4. Start time is not applied in UTC when importing filtered logs using SDK.
- **5.** A user cannot access BioStar 1.93 when using the latest firmware.
- 6. The device cannot recognize iCLASS cards issued by the first generation device.
- 7. Supports unsupported devices (FaceStation 2, FaceLite).
- 8. HID Prox cards are continously recognized.
- 9. The title of the credential input screen is displayed differently on the master device and the slave device when using multiple authentication mode.
- Existing: master device (user ID, user name), slave device (user ID)
- Update: master device and slave device (user ID, user name)
- 10. Relay works after reconnecting for authentication that occurred when elevator connection is disconnected.

From:

https://kb.supremainc.com/knowledge/ -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bep2 revision note 130

Last update: 2021/06/01 08:42