

# Table of Contents

Version 1.0.2 (V1.0.2\_230111) ..... 1

Release ..... 1

New features and improvement ..... 1

Bug Fixes ..... 1

## Version 1.0.2 (V1.0.2\_230111)

### Release

2023-01-20

### New features and improvement

1. Supports a new SE processor and new firmware.
  - Support downgrade to lower version firmware.
2. Fixed incorrect **Partial Modify Fail (Server)** log occurred by changing user information from the server where the user does not exist on the device.

### Bug Fixes

1. When using the relay of the master device for the door, the door does not open when authenticating from the device connected as a slave. (Affects version: v1.0.0)
2. Face authentication does not work when set to low **Baud Rate** in **Serial Setting**. (Affects version: v1.0.0)
3. Missing custom font files other than English and Korean. (Affects version: v1.0.0)
4. When authenticating with face, the Wiegand port outputs an incorrect value as other user information that was previously authenticated with card. (Affects version: v1.0.0)
5. Door Locked event occurs when input signal gets detected while configured to Arm/Disarm by input signal. (Affects version: v1.0.0)
6. Modifying the authentication mode causes other previously set authentication modes to disappear. (Affects version: v1.0.0)
7. The list number column and list column overlaps on the extension number screen. (Affects version: v1.0.0)
8. When issuing a smartcard including a visual face template using the SDK, the card scan screen suddenly disappears. (Affects version: v1.0.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:bs3\\_revision\\_note\\_102](https://kb.supremainc.com/knowledge/doku.php?id=en:bs3_revision_note_102)

Last update: **2023/07/04 18:34**