

## Table of Contents

|                                     |   |
|-------------------------------------|---|
| Version 1.0.0 (V1.0.0_160205) ..... | 1 |
| Release .....                       | 1 |
| Bug fixes .....                     | 1 |
| Version 1.0.0 (V1.0.0_151223) ..... | 1 |
| Release .....                       | 1 |

## Version 1.0.0 (V1.0.0\_160205)

### Release

2016-02-05

### Bug fixes

1. Issue with door relay operation.
2. Issue with alarm lasting time.

## Version 1.0.0 (V1.0.0\_151223)

### Release

2015-12-23

1. Initial firmware developed.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:bsa2\\_revision\\_note\\_100](http://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_100)

Last update: **2021/05/13 15:00**