

Table of Contents

Version 1.7.1 (V1.7.1_200115) 1

 Release 1

 Bug fixes 1

Version 1.7.1 (V1.7.1_200115)

Release

2020-02-05

Bug fixes

1. Changed the firmware downgrade policy

- The kernel of the firmware before the touch panel is replaced has been changed not to downgrade.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_171

Last update: **2021/05/13 10:44**