

Table of Contents

Version 1.0.14 (V1.0.14_160111)	1
Release	1
Bug fixes	1

Version 1.0.14 (V1.0.14_160111)

Release

2016-01-19

Bug fixes

1. OSDP ID is changed to zero and communication is not possible if FW upgrade is performed when connecting to BioStation 2 or BioStation A2 as a slave device.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:dm20_revision_note_1014

Last update: **2021/05/14 10:54**