Table of Contents

/ersion 1.5.0 (V1.5.0_210408)	1
Release	
New Features and Improvements	
Bug Fixes]

Version 1.5.0 (V1.5.0_210408)

Release

2021-04-12

New Features and Improvements

1. The transmission power level for Bluetooth Low Energy (BLE) has been adjusted.

Bug Fixes

- 1. Card data were output with the wrong BitCount while the device was communicating with a 3rd party controller via OSDP. (Affects version: v.1.4.0)
- 2. Modified to output 4 bits for each key input on the keypad while the device was set as a Wiegand reader. (XPD2-GKDPB) (Affects version: v.1.4.0)
- 3. The OSDP LED Temporary command did not work properly. (Affects version: v.1.4.0)
- 4. Delay occurred when reading a smart card that contained credentials which the device did not support while the device was set as a Wiegand reader. (Affects version: v.1.0.0)

From:

https://kb.supremainc.com/knowledge/ -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_rev2_revision_note_150

Last update: 2021/05/28 12:54