Table of Contents

Version 1.3.0 (V1.3.0_200515)	
Release	
New Features and Improvements	
Bug fixes	

/

Version 1.3.0 (V1.3.0_200515)

Release

2020-06-02

New Features and Improvements

- 1. Added feature to change device ID.
- 2. Enhancement in the security of the device.
- Supports secure tamper.
- 3. Changed the color of LED indicator.

Bug fixes

1. A problem where the DESFire smart card is recognized as CSN after restarting the device when the DESFire Advanced setting is in use.

2. A bug where card data is sent with null values.

3. An issue where the device sends 32 bytes of card data regardless of byte values of cards when transferring card data via OSDP communication.

4. A bug where the PIN is sent instead of the smart card ID when authenticating while the device is set as a Wiegand reader using a smart card with private mode set to Card + PIN.

5. A problem where it fails to upgrade the firmware from BioStar 2 when the previous upgrade attempt was done from the Device Manager application but canceled.

6. A bug where the device cannot recognize the smart card after deactivating the Smart Card Layout setting.

From: http://kb.supremainc.com/knowledge/ -

Permanent link: http://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_revision_note_130

Last update: 2021/05/31 08:46

⁻ http://kb.supremainc.com/knowledge/