

Table of Contents

1.0.2 Version (V1.0.2_210614) 1

Release 1

Bug Fixes 1

1.0.2 Version (V1.0.2_210614)

Release

2021-06-18

Bug Fixes

1. Micom firmware upgrade failed intermittently. (Affects version: v1.0.1)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_102

Last update: **2024/04/11 13:16**