

Table of Contents

Version 1.2.1 (V1.2.1_230418) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Version 1.2.1 (V1.2.1_230418)

Release

2023-04-26

XS2-APB, XS2-QAPB and XS2-OAPB types of X-Station 2 model support HID iClass card type through SE processor.

For devices with the new SE processor, after upgrading the firmware to v1.1.4 or higher, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version.

Devices with existing SE processor can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (supremainc.com)

New Features and Improvements

1. Separated event code for QR authentication.
 2. Improved smartcard output byte order setting.
- When using Wiegand or OSDP output, it is improved to be affected by the smartcard output byte order even when the Wiegand output information is as the user ID.

Bug Fixes

1. If the door uses the slave device relay, the door does not open even if authentication succeeds (Affects version: v1.0.0).
2. Device restarts when camera QR authentication using a QR code with large data (Affects version: v1.2.0).
3. Door Locked event occurs when input signal gets detected while configured to Arm/Disarm by input signal (Affects version: v1.0.0).
4. Device does not recognize certain HID iCLASS Seos cards (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_121

Last update: **2024/04/11 13:14**