Table of Contents

Version 1.1.1 (V1.1.1_230621)

Release

2023-06-28

Bug Fixes

1. Device does not recognize certain HID iCLASS Seos cards. (Affects version: v1.0.0)

2. When authenticating with a BLE mobile card running on iOS, authentication fails and the device restarts intermittently. (Affects version: v1.0.0)

3. When a user registered from FaceStation F2 v1.x.x is sent to BioStation 3 through BioStar 2, the device restarts. (Affects version: v1.1.0)

4. Entering ID and PIN to access administrator menu reaches timeout quicker than expected. (Affects version: v1.0.0)

5. When authenticating with a card while face authentication mode is off and QR is disabled, the camera preview screen is displayed after the authentication result appears. (Affects version: v1.0.0)

6. LED indicator operation is maintained even when the device is locked due to an event set in **Trigger & Action**. (Affects version: v1.0.0)

From:
https://kb.supremainc.com/knowledge/ -

Permanent link:
https://kb.supremainc.com/knowledge/doku.php?id=en:bs3_revision_note_111

Last update: **2023/07/04 18:16**