Table of Contents

⚒Fix Me! **This page is not fully translated, yet. Please help completing the translation.**
(remove this paragraph once the translation is finished)

Version 2.6.4 (V2.6.4.0)

Date

2020-02-17

New Features

- Supports the API retrieving logs filtered by EventMask
- Supports DesFire Advanced format setting
- Supports the card type selection feature
- Supports duplicate fingerprints/face check

1. The API retrieving logs filtered by Event Mask so that you can use memory efficiently than before.

- Structure BS2EventSmallBlob has been added
- API BS2_GetLogSmallBlob has been added
- API BS2_GetLogSmallBlobFromDir has been added

2. DesFire Advanced format setting is now supported.

- Structure BS2SimpleDeviceInfoEx has been added
- Structure BS2DesFireCardConfigEx has been added
- API BS2_GetDesFireCardConfigEx has been added
- API BS2_SetDesFireCardConfigEx has been added

3. Card type selection is available so that you can select/deselect the card type you want to read fro the device.

- Structure BS2SystemConfig has been added
- API BS2_SetSystemConfig has been added

4. Duplicate fingerprint and face check is available.

- Structure BS2FaceConfig has been added
- API BS2_GetFingerprintConfig has been added
- API BS2_SetFingerprintConfig has been added
- Structure BS2FingerprintConfig has been added
- API BS2_GetFaceConfig has been added
- API BS2_SetFaceConfig has been added

Modified Features

1. Fixed the issue of device malfunctioning and rebooting when BS2Job.numJobs in BS2UserBlobEx exceeds the maximum value 16.

- Refer to structure BS2UserBlobEx
- Refer to API BS2_VerifyUserEx
- Refer to API BS2_IdentifyUserEx
- Refer to API BS2_EnrolUserEx
- Refer to API BS2_VerifyUserSmallEx
- Refer to API BS2_IdentifyUserSmallEx
- Refer to API BS2_EnrollUserSmallEx

2. Fixed the issue of BioStation 2 not available for user images.

3. Fixed the error BS_SDK_INVALID_CODE_SIGN when upgrading SIO2.

4. Fixed the error BS_SDK_ERROR_NOT_SUPPORTED when calling BS2_GetCardModel for BLN2-PAB.

- Refer to API BS2_GetCardModel

5. Fixed the issue that SDK doesn't recognize device disconnection when the device is constantly disconnected.

6. Fixed the issue of Linux SDK crash.

From:
http://kb.supremainc.com/bs2sdk/ - **BioStar Device SDK**

Permanent link:
http://kb.supremainc.com/bs2sdk/doku.php?id=en:release_note_2640&rev=1581990676

Last update: **2020/02/18 10:51**