Table of Contents

Version 1.6.1 (V1.6.1_210324)

Release

2021-04-22

New Features and Improvements

1. Upgraded to the 1.1.1i version of OpenSSL.

2. Intelligent Slave Support

- Intelligent Slave: A function that enables 1:1 or 1:N matching directly from the Suprema device and transmits the authentication result as OSDP card data to the third-party controller.

3. Separated event logs of Mobile Access cards and RFID cards.

4. Improved that LFD Driver IC damage does not affect fingerprint recognition performance.

Bug fixes

1. If 31 slave devices were connected and one of the devices got disconnected, the master device rebooted. (Affects version: v1.0.0)

2. Incorrect BitCount was sent if a user authenticated with AoC when the device was connected to a 3rd-party system via OSDP. (Affects version: v1.0.0)

3. The device responded that it supported transparent mode by OSDP_PDCAP when connecting as a slave while it did not support it. (Affects version: v1.0.0)

4. It was not able to change secure tamper settings from the device menu. (Affects version: v1.6.0)

5. The fingerprint recognition function worked even when a Secure-IC error occurred. (Affects version: v1.6.0)

6. When calling the BS2_ResetConfigExceptNetInfo API from the BioStar 2 Device SDK, a 'Timeout' error occurred. (Affects version: v1.0.0)

7. It was able to communicate using default keys after changing the key settings when the device was connected to a 3rd-party device via OSDP. (Affects version: v1.5.0)

From:
https://kb.supremainc.com/knowledge/ -

Permanent link:
https://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_161

Last update: **2021/05/17 12:02**