Table of Contents

Firmware Version 1.0.3 (Build No. 1.0.3_250929)

Release

2025-10-21

> - After upgrading the firmware to v1.0.3, it is not able to downgrade to an earlier version of the firmware.
> - For more information, check the serial number of the device and contact the Suprema (https://supremainc.com).

Bug Fixes

1. CPU usage rises to as high as 100% and user enrollment is delayed. (Affects version: v1.0.0)

From:
https://kb.supremainc.com/knowledge./ -

Permanent link:
https://kb.supremainc.com/knowledge./doku.php?id=en:cs20_revision_note_103

Last update: **2025/10/27 13:03**