Table of Contents

Version 2.6.4 (V2.6.4.1)

Date

2020-02-25

New Features

- Supports the API retrieving logs filtered by EventMask
- Supports DesFire Advanced format setting
- Supports the card type selection feature
- Supports duplicate fingerprints/face check

1. The API retrieving logs filtered by Event Mask so that you can use memory efficiently than before.

- Refer to structure BS2EventSmallBlob
- Refer to API BS2_GetLogSmallBlob
- Refer to API BS2_GetLogSmallBlobFromDir

2. DesFire Advanced format setting is now supported.

- Refer to structure BS2SimpleDeviceInfoEx
- Refer to structure BS2DesFireCardConfigEx
- Refer to API BS2_GetDesFireCardConfigEx
- Refer to API BS2_SetDesFireCardConfigEx

3. Card type selection is available so that you can select/deselect the card type you want to read fro the device.

- Refer to structure BS2SystemConfig
- Refer to API BS2_SetSystemConfig

4. Duplicate fingerprint and face check is available.

- Refer to structure BS2FaceConfig
- Refer to API BS2_GetFingerprintConfig
- Refer to API BS2_SetFingerprintConfig
- Refer to structure BS2FingerprintConfig
- Refer to API BS2_GetFaceConfig
- Refer to API BS2_SetFaceConfig

Modified Features

1. Fixed the issue of device malfunctioning and rebooting when BS2Job.numJobs in BS2UserBlobEx

exceeds the maximum value 16.

- Refer to structure BS2UserBlobEx
- Refer to API BS2_VerifyUserEx
- Refer to API BS2_IdentifyUserEx
- Refer to API BS2_EnrolUserEx
- Refer to API BS2_VerifyUserSmallEx
- Refer to API BS2_IdentifyUserSmallEx
- Refer to API BS2_EnrollUserSmallEx

2. Fixed the issue of BioStation 2 not available for user images.

3. Fixed the error BS_SDK_INVALID_CODE_SIGN when upgrading SIO2.

4. Fixed the error BS_SDK_ERROR_NOT_SUPPORTED when calling BS2_GetCardModel for BLN2-PAB.

- Refer to API BS2_GetCardModel

5. Fixed the issue that SDK doesn't recognize device disconnection when the device is constantly disconnected.

6. Fixed the issue of Linux SDK crash.