Table of Contents

Version 1.7.0 (V1.7.0_220921)

Release

2022-09-21

New Features and Improvements

1. Supports a new BLE (Bluetooth Low Energy) chip.

- The BLE chip parts of the hardware have been changed, and the firmware has been upgraded to be compatible with both the existing and new BLE chips.

2. Improved setting of the byte order for smart cards.

- Improved to display valid values through Wiegand or OSDP when the AoC (Access on Card) ID issued by BioStar 2 is set to Alphanumeric.

Bug Fixes

1. Intermittent Mobile Card not authenticating (Affects version: v1.4.0).

- Improved BLE Micom Firmware and BLE Recovery RFCore.

2. When FaceStation F2 and Xpass D2 are connected as master-slave, Xpass D2 cannot authenticate with Mobile Card (Affects version: v1.4.0).