

Table of Contents

Version 1.4.2 (V1.4.2_211018)	1
Release	1
Bug Fixes	1

Version 1.4.2 (V1.4.2_211018)

Release

2021-10-22

Bug Fixes

1. When upgrading firmware from v1.1.0 or earlier to v1.4.1, the device failed and could not be recovered. (Affects version: v1.1.0 or earlier)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bep2_revision_note_142

Last update: **2024/06/12 10:20**