

Table of Contents

| | |
|-------------------------------------|---|
| Version 1.3.0 (V1.3.0_190626) | 1 |
| Release | 1 |
| New Features and Improvements | 1 |
| Bug Fixes | 1 |

Version 1.3.0 (V1.3.0_190626)

Release

2019-07-12

New Features and Improvements

1. OSDP Standardization

- Improved to comply with OSDP V2.1.7 protocol when connecting with 3rd-party controllers.

2. Supports options for selection by card type.

3. Supports the latest version of I/O module Micom (V1.3.1).

4. Firmware upgrade status is added to LED status indicator.

Bug Fixes

1. Applies FA improvement algorithm.

2. Authentication results are printed after LED status indicator changes color to normal during authentication.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:ber2_revision_note_130

Last update: **2021/06/01 13:09**