

Table of Contents

Version 1.3.1 (V1.3.1_190829)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.3.1 (V1.3.1_190829)

Release

2019-09-19

New Features and Improvements

1. Improved the speed at which the device recognizes 13.56 MHz cards.

Bug Fixes

1. The device recognizes the DESFire(Adv) card as a CSN if the device is restarted when the smart card layout set as DESFire(Adv).

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:ber2_revision_note_131

Last update: **2021/06/01 13:08**