Table of Contents

Version 1.6.0 (V1.6.0 200902)	1
Release	
Bug Fixes	

Version 1.6.0 (V1.6.0_200902)

Release

2020-09-10

New Features and Improvements

- 1. Supports Secure Boot.
- BEW2-OAPB, BEW2-OHPB, BEW2-ODPB
- 2. Supports Mobile Access.
- BEW2-OAP, BEW2-OHP, BEW2-ODP: NFC
- BEW2-OAPB, BEW2-OHPB, BEW2-ODPB: BLE, NFC
- 3. Separated event logs of Mobile Access cards and RFID cards.

Bug Fixes

- 1. iCLASS card does not get read as a Wiegand card unless the iCLASS was also selected on the Smart Card mask.
- 2. Device responded that it supports transparent mode by OSDP_PDCAP when connecting as slave while it does not support it.
- 3. When using a static IP while DNS server address is configured, a reboot on the device causes communication problems between the server.
- 4. Incorrect BitCount is sent if a user authenticates with AoC when the device is connected to a 3rd-party system via OSDP.
- 5. If 31 slave devices are connected and one of the devices get disconnected, the master device will reboot.

From:

https://kb.supremainc.com/knowledge/ -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2 revision note 160

Last update: 2021/05/28 10:52

⁻ https://kb.supremainc.com/knowledge/

⁻ https://kb.supremainc.com/knowledge/