

# Table of Contents

Version 1.1.0 (V1.1.0_150819) .....	1
Release .....	1
Bug Fixes .....	1

# Version 1.1.0 (V1.1.0\_150819)

## Release

2015-08-19

## Bug Fixes

1. LSB recognition problem with DESFire cards.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:bs2\\_revision\\_note\\_110\\_1](http://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_110_1)

Last update: **2021/05/14 11:40**