

Table of Contents

Version 1.4.1 (V1.4.1_170727)	1
Release	1
Bug Fixes	1

Version 1.4.1 (V1.4.1_170727)

Release

2017-07-31

Bug Fixes

1. Issue where the device cannot recognize SEOS smart cards when multi-credential authentication mode (iCLASS SEOS card + Fingerprint) is used continuously.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_141_1

Last update: **2021/05/14 12:10**