

# Table of Contents

Version 1.7.1 (V1.7.1_240130) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fix .....	1

# Version 1.7.1 (V1.7.1\_240130)

## Release

2024-02-06

## New Features and Improvements

1. Supports **Wireless Door Lock**.
2. Improved synchronization to complete if user enrollment fails when synchronizing multiple users to the device in BioStar 2.
3. Improved to select and update only the desired information when updating user information. (Compatible with BioStar v2.9.0 or higher)
4. Supports new devices.
  - BioStation 2a

## Bug Fix

1. When using **Server Matching, Card + Face** or **ID + Face** authentication fails on FaceStation 2 connected as a slave. (Affects version: v1.4.0)
2. Resource file update fails on the device connected as a slave. (Affects version: v1.5.2)
3. After authenticating with **ID + Face** on a device connected as a slave, the **ID Input** screen does not appear when the **ID** icon is touched. (Affects version: v1.0.0)
4. Slave device that is set to be locked will not be locked if **Secure Tamper** occurs on the master device. (Affects version: v1.4.0)
5. The settings of the connected IM-120 are not being applied. (Affects version: v1.6.1)
6. Authentication fails when authenticating with a DESFire AoC while the device is connected as a slave. (Affects version: v1.0.0)
7. Device abnormally restarts when changing the device's **Network** settings in BioStar 2. (Affects version: v1.0.0)
8. When settings that are not supported are configured through the SDK, the device fails to boot

properly. (Affects version: v1.0.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:cs40\\_revision\\_note\\_171](http://kb.supremainc.com/knowledge/doku.php?id=en:cs40_revision_note_171)

Last update: **2024/02/14 10:56**