

Table of Contents

Firmware Version 1.0.2 (Build No. 1.0.2_250924) 1

Release 1

Bug Fixes 1

Firmware Version 1.0.2 (Build No. 1.0.2_250924)

Release

2025-10-21

Bug Fixes

1. CPU usage rises to as high as 100%. (Affects version: v1.0.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:di-24_revision_note_102

Last update: **2025/10/27 14:18**