

Table of Contents

Version 1.0.13 (V1.0.13_150810)	1
Release	1
New Features and Improvements	1
Bug fixes	1

Version 1.0.13 (V1.0.13_150810)

Release

2015-08-10

New Features and Improvements

1. Output the NACK signal when SecuBlock error occurs.
2. Change Wiegand Input Interval Time.
3. Reset the setting values of Supervised Input when press INIT button.

Bug fixes

1. Displays incorrect port number when Supervised Input port is grounded several times.

From:
<http://kb.supremainc.com/knowledge/> -

Permanent link:
http://kb.supremainc.com/knowledge/doku.php?id=en:dm20_revision_note_1013

Last update: **2021/05/14 10:58**