

Table of Contents

Version 1.0.15 (V1.0.15_160429)	1
Release	1
Bug fixes	1

Version 1.0.15 (V1.0.15_160429)

Release

2016-12-08

Bug fixes

1. Communication is not possible when encountered a packet size exceeding the maximum OSDP packet queue.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:dm20_revision_note_1015

Last update: **2021/05/14 10:52**