

# Table of Contents

Version 1.2.0 (V1.2.0_200604) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fixes .....	1

# Version 1.2.0 (V1.2.0\_200604)

## Release

2020-06-05

## New Features and Improvements

1. Added feature to change device ID.

## Bug Fixes

1. Mac error occurs when RS-485 communication does not comply with OSDP standard.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:dm20\\_revision\\_note\\_120](https://kb.supremainc.com/knowledge/doku.php?id=en:dm20_revision_note_120)

Last update: **2021/05/14 10:13**