

Table of Contents

Version 1.1.3 (V1.1.3_211208) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Version 1.1.3 (V1.1.3_211208)

Release


2021-12-13

New Features and Improvements

1. Supports the firmware compatibility according to dualization for the front cover (LCD & touch pad).
 - Changed the firmware of the touch pad panel to be upgraded according to the type of LCD when replacing the front cover.
2. Improved to extract a new visual face template from the warped image only if necessary after checking the template version (Algorithm compatibility) when sending templates from BioStar 2 or BioStar 2 Device SDK.
3. Improved security vulnerability.
 - Removed UDP port for debug.

Bug Fixes

1. Slave devices were disconnected when the master device was rebooted (Affects version: v1.1.2 or earlier).
2. The device failed to recognize the iCLASS Seos card suddenly (FSF2-AB) (Affects version: v1.1.2 or earlier).
3. When synchronizing user data from the device to the BioStar2 server and retransmitting it to the device, only some users were transmitted or took a long time to transmit.
 - When a low-quality visual face warped image is synchronized to another device, the synchronization speed is slowed down by continuously retrying synchronization after the template extraction fails on that device due to the low quality (Affects version: v1.1.2 or earlier).
4. If the 'Access Granted' event was set in Trigger & Action, the temperature was abnormally displayed as 'NaN' when a user authenticated on the device (Affects version: v1.1.0 or later, v1.1.2 or earlier).



From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_113&rev=1639534066

Last update: **2021/12/15 11:07**