

# Table of Contents

Version 1.2.0 (V1.2.0_200624) .....	1
Release .....	1
New Features and Improvements .....	1
Bug fixes .....	1

# Version 1.2.0 (V1.2.0\_200624)

## Release

2020-07-09

## New Features and Improvements

1. Added feature to change device ID.

## Bug fixes

1. Mac error occurs when RS-485 communication does not comply with OSDP standard.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:om120\\_revision\\_note\\_120](http://kb.supremainc.com/knowledge/doku.php?id=en:om120_revision_note_120)

Last update: **2021/05/18 08:19**