

# Table of Contents

Version 1.1.4 (V1.1.4_150626) .....	1
Release .....	1
Bug fixes .....	1

# Version 1.1.4 (V1.1.4\_150626)

## Release

2015-06-26

## Bug fixes

1. Issue with RS-485 data reception.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:sio2\\_revision\\_note\\_114](https://kb.supremainc.com/knowledge/doku.php?id=en:sio2_revision_note_114)

Last update: **2021/05/18 09:35**