

# Table of Contents

Version 1.2.4 (V1.2.4_181031) .....	1
Release .....	1
New Features and Improvements .....	1
Bug fixes .....	1

# Version 1.2.4 (V1.2.4\_181031)

## Release

2018-11-29

## New Features and Improvements

1. If the data transmission fails when communicating with OSDP, it is transmitted again.
2. When there is the response data with OSDP Secure Session, it responds with 0x16 for SEC\_BLK\_TYPE value and responds with 0x18 when there is no data.

## Bug fixes

1. Problems with data communication when changing RS485 baud rate to 9600 bps with osdp\_COMSET command.

From:  
<http://kb.supremainc.com/knowledge/> -

Permanent link:  
[http://kb.supremainc.com/knowledge/doku.php?id=en:sio2\\_revision\\_note\\_124](http://kb.supremainc.com/knowledge/doku.php?id=en:sio2_revision_note_124)

Last update: **2021/05/18 08:50**