

Table of Contents

FaceStation F2 Revision Notes

1

FaceStation F2 Revision Notes

- After upgrading the firmware to v2.x.x, it is not able to downgrade to an earlier version (v1.x.x) firmware.
- When upgrading the firmware from v1.x.x to v2.x.x, it is recommended to use BioStar 2 or BioStar 2 Device SDK.
- When upgrading the firmware using a USB memory inevitably, first set **Menu Timeout to Always On** in the **Display & Sound** menu before proceeding with the upgrade. Also, even if a failure message is displayed during the upgrade, DO NOT remove the USB memory and wait until a success message is displayed. The device will restart automatically when the upgrade is complete.

- [Version 2.2.0 \(V2.2.0_240704\)](#)
2024-07-10
- [Version 2.1.4 \(V2.1.4_230810\)](#)
2023-08-11
- [Version 2.1.3 \(V2.1.3_230525\)](#)
2023-05-30
- [Version 2.1.2 \(V2.1.2_230130\)](#)
2023-02-01
- [Version 2.1.1 \(V2.1.1_221130\)](#)
2022-11-30
- [Version 2.1.0 \(V2.1.0_221005\)](#)
2022-10-05
- [Version 2.0.3 \(V2.0.3_220705\)](#)
2022-07-15
- [Version 2.0.2 \(V2.0.2_220502\)](#)
2022-05-10
- [Version 1.1.4 \(V1.1.4_220315\)](#)
2022-03-22
- [Version 1.1.2 \(V1.1.2_210903\)](#)
2021-10-01
- [Version 1.1.1 \(V1.1.1_210623\)](#)
2021-06-25
- [Version 1.0.5 \(V1.0.5_210422\)](#)
2021-05-06
- [Version 1.0.4 \(V1.0.4_210303\)](#)
2021-03-10
- [Version 1.0.3 \(V1.0.3_210126\)](#)
2021-02-02

- [Version 1.0.2 \(V1.0.2_210104\)](#)
2021-01-05
- [Version 1.0.1 \(V1.0.1_201110\)](#)
2020-11-13
- [Version 1.0.0 \(V1.0.0_200915\)](#)
2020-09-15

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:tc_prod_f2&rev=1722479022

Last update: **2024/08/01 11:23**