

# Table of Contents

Version 1.5.0 (V1.5.0_210408) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fixes .....	1

# Version 1.5.0 (V1.5.0\_210408)

## Release

2021-04-12

## New Features and Improvements

1. The transmission power level for Bluetooth Low Energy (BLE) has been adjusted.

## Bug Fixes

1. Card data were output with the wrong BitCount while the device was communicating with a 3rd party controller via OSDP. (Affects version: v.1.4.0)
2. Modified to output 4 bits for each key input on the keypad while the device was set as a Wiegand reader. (XPD2-GKDPB) (Affects version: v.1.4.0)
3. The OSDP LED Temporary command did not work properly. (Affects version: v.1.4.0)
4. Delay occurred when reading a smart card that contained credentials which the device did not support while the device was set as a Wiegand reader. (Affects version: v.1.0.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2\\_rev2\\_revision\\_note\\_150](https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_rev2_revision_note_150)

Last update: **2021/05/28 12:54**