

# Table of Contents

Version 1.1.0 (V1.1.0_181129) .....	1
Release .....	1
New Features and Improvements .....	1
Bug fixes .....	1

# Version 1.1.0 (V1.1.0\_181129)

## Release

2018-11-30

## New Features and Improvements

1. Support to BioStar 2 Device Manager.
2. If the data transmission fails when communicating with OSDP, it is transmitted again.
3. Support to DESFire/DESFire EV1 Advanced option.
4. Support to AES encryption type for DESFire card.

## Bug fixes

1. Modified to upgrade the firmware only if it is a raw data.
2. The device cannot read CSN because the card recognized as an NFC tag.
3. When communicating with OSDP, the LED color is displayed differently from the setting.
4. The device does not reboot when initializing the device settings.
5. The maximum value of the Wiegand input interval is output differently from the setting.
6. A beep sound occurs even when there is no action or event on the device.
7. A beep sound occurs differently from the setting.

From:  
<https://kb.supremainc.com/knowledge/> -

Permanent link:  
[https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2\\_revision\\_note\\_110](https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_revision_note_110)

Last update: **2021/05/31 09:29**