

Table of Contents

Version 1.1.1 (V1.1.1_161213)	1
Release	1
Bug Fixes	1

Version 1.1.1 (V1.1.1_161213)

Release

2016-12-20

Bug Fixes

1. Issue that cannot detect the device with UDP in BioStar 1.92.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_111

Last update: **2021/05/28 12:19**