

Table of Contents

Version 1.1.2 (V1.1.2_170213)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.1.2 (V1.1.2_170213)

Release

2017-02-27

New Features and Improvements

1. Add Lift I/O MFG Command

Bug Fixes

1. Issue where the slave device's time zone is changes when the device synchronization is perfomed.
2. Wiegand Output malfunctions when fingerprint authentication is completed after authenticating with the unregistered card
3. Slow-downs the performance.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_112

Last update: **2021/05/28 12:16**