

# Table of Contents

Version 1.0.1 (V1.0.1_150423) .....	1
Release .....	1
Bug Fixes .....	1

## Version 1.0.1 (V1.0.1\_150423)

### Release

2015-04-23

### Bug Fixes

1. Fingerprint can't be input when using both anti-passback and dual mode authentication.
2. Card information read erroneously when the card's byte order is changed to LSB.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:bs2\\_revision\\_note\\_101](https://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_101)

Last update: **2021/05/14 11:34**