

Table of Contents

Version 1.10.2 (V1.10.2_240715)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.10.2 (V1.10.2_240715)

Release

2024-07-19

New Features and Improvements

1. Improved to ensure that values set with osdp_comset are correctly applied on the device connected as a slave.
2. Improved to get user update succeeded event log using the GetLogWithFilter function in the SDK.

Bug Fixes

1. Migration malfunction occurs when the firmware is upgraded from v1.6.1 to v1.10.1. (Affects version: v1.9.0)
 - Migration did not complete and the device boots to the main screen, some keys do not work or an abnormal screen is displayed.
2. Device does not recognize certain HID iCLASS Seos cards. (Affects version: v1.0.0)
3. The user ID stored as a 32-character string is truncated to only 31 characters in a specific event log. (Affects version: v1.0.0)
4. Intermittently, the door does not open even if authentication succeeds when the door uses the slave device's relay. (Affects version: v1.0.0)
5. When a user with a 32-character user ID authenticates to the device while the device is not connected to the server, the authentication event log is not updated in BioStar 2 even after the device is reconnected to the server. (Affects version: v1.0.0)
6. When a device is connected to **Wireless**, turning off the power to the wireless AP, restarting the device, and then turning the wireless AP back on causes Wireless to not automatically reconnect. (Affects version: v1.0.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bs2_revision_note_1102

Last update: **2024/08/01 11:58**