

Table of Contents

Version 1.0.1 (V1.0.1_221020)	1
Release	1
New features and improvement	1
Bug Fixes	1

 **Fix Me!** This page is not fully translated, yet. Please help completing the translation.
(remove this paragraph once the translation is finished)

Version 1.0.1 (V1.0.1_221020)

Release

2022-10-21

New features and improvement

1. Improved motion detection performance for low-light environments.
2. Improved Visual Face matching algorithm.
3. Improved all pop-up messages displayed on the device to operate according to the time set in **Message Timeout**.
4. Fixed Korean and English strings in the **RTSP** menu.

Bug Fixes

1. When upgrading resources or firmware from BioStar 2, the device could not check the progress of the upgrade because no information was displayed. (Affects version: v1.0.0)
2. When synchronizing multiple users to a device in BioStar 2 and then restarting the device, the **User Usage** on the device displays a different number of visual faces than the number of synchronized. (Affects version: v1.0.0)
3. When entering the device detail page after adding a logo image to the device connected as a slave, an Invalid payload error occurs and the RS-485 get disconnected. (Affects version: v1.0.0)
4. When **Device Hashkey Management** is set to **Use** in BioStar 2 and migration proceeds, all users are deleted from the device, but a delete notification pop-up is not displayed. (Affects version: v1.0.0)
(: v1.0.0)
5. Device hangs intermittently and then restarts. (Affects version: v1.0.0)
6. When entering the **Wireless**, the new SSID does not appear, but only the previously searched SSID

appears. (Affects version: v1.0.0)

7. When enrolling a visual face or card on a device using the BioStar 2, the scan screen is not visible and the screen saver state remains. (Affects version: v1.0.0)

8. When the call button on the main screen is pressed with only one extension number stored in the device, it does not connect directly. (Affects version: v1.0.0)

9. In **Edit User**, if you select **Extended Private Auth Mode** as **ID + Fingerprint/PIN** and press **OK**, the fingerprint icon is incorrectly displayed as a face icon in the **Extended Private Auth Mode** list. (Affects version: v1.0.0)

10. Authentication failure occurs when authenticating with AoC with private auth mode set to **Card + Face**. (Affects version: v1.0.0)

11. When the device is restarted via BioStar 2, only a notification sound plays and the restart pop-up message does not appear. (Affects version: v1.0.0)

12. Firmware upgrade via USB restarts the device without a success or failure popup message. (Affects version: v1.0.0)

13. In BioStar 2's **T&A** menu, the **Schedule** display part is blank when creating a **T&A Code** with a **Schedule** other than **Always** and selecting the **T&A Code** on the device. (Affects version: v1.0.0)

14. Memory usage incorrectly displayed in **DRAM Usage** in **Memory Info**. (Affects version: v1.0.0)

15. When entering the menu from a device connected as a slave, a normal menu touch sound plays instead of a warning sound. (Affects version: v1.0.0)

16. When enrolling a visual face in the **USER** menu in BioStar 2, when the scan waiting time exceeded while enrolling the 1st face and then scanning the 2nd face, the face enrolled in the 1st appears. (Affects version: v1.0.0) (KB 000: v1.0.0)

17. If the network is connected to a wireless LAN and then enters **Wireless** again after changing to an ethernet connection, the wireless AP list is not displayed. (Affects version: v1.0.0)

18. Wiegand 0000 0000 0000 00 00 0 0000 000000 0000 00 (KB 000: v1.0.0)

19. 0000 IP 0000 000000 00 0000 00 00 00 000000 000000 000000 00 (KB 000: v1.0.0)

20. 0000 00 000000 00000000 00 0000 000000 00 000000 000000 000000 000000 00 00 (KB 000: v1.0.0)

21. 0000 00000000 000000 00 000000 00000000 0000 00 0000 000000 00 (KB 000: v1.0.0)

22. 0000 00000000 0 0000 00 00 00 0000 0000 000000 BioStar 2 00 0000 IP 000000 00 0 0000 000000 00 00 0000 0000 00 0000 000000 00 (KB 000: v1.0.0)

23. 00 0000 000000 000000 000000 0000 000000 000000 000000 00 (KB 000: v1.0.0)

24. 0000 00 0000 00 0 0000 00000000 0000 0000 00 (KB 000: v1.0.0)

- 48. [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] (Version: v1.0.0)
- 49. [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] (Version: v1.0.0)
- 50. [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] (Version: v1.0.0)
- 51. BioStar 2 [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] LAN [Placeholder] [Placeholder] [Placeholder] [Placeholder] (Version: v1.0.0)
- 52. IP [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] (Version: v1.0.0)
- 53. [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] [Placeholder] (Version: v1.0.0)
- 54. [Placeholder] [Placeholder] MAC [Placeholder] [Placeholder] [Placeholder] VFMCore [Placeholder] [Placeholder] [Placeholder] [Placeholder] (Version: v1.0.0)
- 55. [Placeholder] (Version: v1.0.0)

From:
<https://kb.supremainc.com/knowledge/> -

Permanent link:
https://kb.supremainc.com/knowledge./doku.php?id=en:bs3_revision_note_101&rev=1666598871

Last update: **2022/10/24 17:07**