Table of Contents

Firmware Version 1.0.2 (Build No. 1.0.2_250714)	1
Release	1
Bug Fixes	1

Firmware Version 1.0.2 (Build No. 1.0.2_250714)

Release

2025-07-15

Bug Fixes

1. After enabling the **Secure communication with device** option and transferring the certificate to the device in BioStar 2, the device cannot connect to the server. (Affects version: v1.0.0)

From:

https://kb.supremainc.com/knowledge/ -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:cs20_revision_note_102

Last update: 2025/07/17 08:36