

# Table of Contents

Version 1.3.1 (V1.3.1_191203) .....	1
Release .....	1
New Features and Improvements .....	1
Bug fixes .....	1

# Version 1.3.1 (V1.3.1\_191203)

## Release

2019-12-03

## New Features and Improvements

1. Supports CoreStation Setup Manager.

## Bug fixes

1. The list of connected slave devices is initialized if rebooting the master device after changing the RS-485 baudrate.
2. When using firmware V1.3.0 the connection to the I/O device that using the firmware version below is lost.
  - DM-20 FW V1.1.2 and below
  - OM-120 FW V1.0.0 and below
  - Secure I/O 2 FW V1.2.1 and below

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:cs40\\_revision\\_note\\_131](http://kb.supremainc.com/knowledge/doku.php?id=en:cs40_revision_note_131)

Last update: **2021/05/25 09:13**