

# Table of Contents

Version 1.3.1 (V1.3.1_211203) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fixes .....	1

# Version 1.3.1 (V1.3.1\_211203)

## Release

2021-12-13

## New Features and Improvements

1. Applied a code to compensate for the incorrect flag of the face template.
  2. Improved security vulnerability.
- Removed UDP port for debug.

## Bug Fixes

1. Scanning a fingerprint to enroll on the slave device caused an error and failed enrollment (Affects version: v1.3.0).
2. Abnormal authentication failure occurred if a user authenticates with card+face or ID+face on the slave device when using server matching (Affects version: v1.2.0, v1.3.0).
3. Slave devices are disconnected when the master device is rebooted (Affects version: v1.3.0 or earlier).
4. When enrolling a face, even though the device detected the user's face successfully, the color of the guideline on the screen was not displayed properly (Affects version: v1.3.0).
5. Abnormal authentication failure occurred when the slave device's auth mode was set to card+fingerprint (Affects version: v1.2.0 or later, v1.3.0 or earlier).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:fl\\_revision\\_note\\_131&rev=1639544945](http://kb.supremainc.com/knowledge/doku.php?id=en:fl_revision_note_131&rev=1639544945)

Last update: **2021/12/15 14:09**