

# Table of Contents

Version 1.3.3 (V1.3.3_221118) .....	1
Release .....	1
Bug Fixes .....	1

# Version 1.3.3 (V1.3.3\_221118)

## Release

2022-11-24

## Bug Fixes

1. Dot(.) is not entered when configuring **IP address** after configuring a specific menu (Affects version: v1.0.0).
2. When the LAN cable connected to the device is disconnected and reconnected, it takes a long time for IP to be assigned by DHCP (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge./doku.php?id=en:fl\\_revision\\_note\\_133&rev=1669339706](http://kb.supremainc.com/knowledge./doku.php?id=en:fl_revision_note_133&rev=1669339706)

Last update: **2022/11/25 10:28**