

Table of Contents

Version 1.3.4 (V1.3.4_230110)	1
Release	1
Bug Fixes	1

Version 1.3.4 (V1.3.4_230110)

Release

2023-02-02

Bug Fixes

1. If there is a face credential enrolled through an abnormal path and not assigned to a user, the device freezes at the logo screen while booting and does not complete normally (Affects version: v1.0.0).

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fl_revision_note_134

Last update: **2023/02/07 09:46**