

Table of Contents

Version 1.5.1 (V1.5.1_211203)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.5.1 (V1.5.1_211203)

Release

2021-12-13

New Features and Improvements

1. Applied a code to compensate for the incorrect flag of the face template.
 2. Improved security vulnerability.
- Removed UDP port for debug.

Bug Fixes

1. Scanning a fingerprint to enroll on the slave device caused an error and failed enrollment (Affects version: v1.5.0).
2. The device failed to recognize the iCLASS Seos card suddenly (FS2-AWB) (Affects version: v1.5.0 or earlier).
3. Abnormal authentication failure occurred if a user authenticates with card+face or ID+face on the slave device when using server matching (Affects version: v1.5.0 or earlier).
4. Slave devices are disconnected when the master device is rebooted. (Affects version: v1.5.0 or earlier).
5. Abnormal authentication failure occurred when the slave device's auth mode was set to card+fingerprint (Affects version: v1.4.0 or later, v1.5.0 or earlier).

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_151

Last update: **2021/12/16 08:12**