

# Table of Contents

Version 1.0.1 (V1.0.1_191030) .....	1
Release .....	1
New features and improvements .....	1
Bug fixes .....	1

# Version 1.0.1 (V1.0.1\_191030)

## Release

2019-11-07

## New features and improvements

1. Added a logic to prevent FA(False Acceptance) for the fingerprint authentication.
2. Applied the latest Android security patch.
  - Patch level: August 5, 2019.
3. Support for the Ethernet setting API.
4. Remove some Android applications
  - Improved the issue that error messages occur caused by some unnecessary applications.

## Bug fixes

1. Android OS reboots intermittently after the fingerprint sensor is reset.
2. The device reboots abnormally if a user leaves the AP unconnected after turning on the Wi-Fi.
3. The device reboots if a user authenticates the fingerprint consecutively for a long time.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:omnis\\_revision\\_note\\_101](http://kb.supremainc.com/knowledge/doku.php?id=en:omnis_revision_note_101)

Last update: **2021/05/18 10:20**