

# Table of Contents

Version 1.7.2 (V1.7.2_231102) .....	1
Release .....	1
Bug Fixes .....	1

# Version 1.7.2 (V1.7.2\_231102)

## Release

2023-11-03

Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.7.0 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (supremainc.com)

## Bug Fixes

1. When running the Device Manager application v1.1.8 on iOS, certain devices do not connect. (Affects version: v1.7.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:xpd2\\_rev2\\_revision\\_note\\_172&rev=1701064348](http://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_rev2_revision_note_172&rev=1701064348)

Last update: **2023/11/27 14:52**