

Table of Contents

Version 1.1.3 (V1.1.3_220225)	1
Release	1
Bug Fixes	1

Version 1.1.3 (V1.1.3_220225)

Release

2022-03-08

Bug Fixes

1. The QR/Barcode scan guidance message on screen operated differently from QR/Barcode Scan Timeout setting (XS2-QAPB, XS2-QDPB) (Affects version: v1.0.0).
2. When authenticated using fingerprints, the relay did not work as set in the device menu (XS2-OAPB, XS2-ODPB) (Affects version: v1.1.0).
3. When the dual authentication was set on the device, if the fake fingerprint was used in the second authentication, a screen unrelated to the situation was output after authentication failure (XS2-OAPB, XS2-ODPB) (Affects version: v1.1.0).
4. Image logs were taken abnormally in an environment where the device is exposed to strong light (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_113

Last update: **2022/03/16 09:02**