

Table of Contents

Version 1.2.2 (V1.2.2_230602)	1
Release	1
Bug Fixes	1

Version 1.2.2 (V1.2.2_230602)

Release

2023-06-08

Bug Fixes

1. Device abnormally restarts when Image Log is Enabled and image log is logged on the device. (Affects version: v1.2.0)
2. When authenticating with a BLE mobile card running on iOS, authentication fails and the device restarts intermittently. (Affects version: v1.0.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_122&rev=1686534013

Last update: **2023/06/12 10:40**